
From: Wurfel, Brad (DEQ)
Sent: Monday, November 30, 2015 1:16 PM
To: Brown, Jessica (GOV); Murray, David (GOV)
Subject: FW: Eisenhower
Attachments: EisenhowerElementary_Report.pdf

Here's the final version of the Eisenhower report.

With little deviation, the pattern we're seeing emerge now that we've tested 8 schools is that old faucets and drinking fountain bubblers (which should have been replaced in the 80s) are the source of any lead we are finding in the schools testing.

This is worth noting because it's entirely likely that many of the old homes in Flint -- and, for that matter, elsewhere in the state -- are probably in similar situation to the schools. The conversation thus far has been focused on lead service lines, but another considerable transmission source is old faucets, or copper plumbing with the 50-50 lead solder that was once common.

We're inclined to post the most recent report on the heels of the DHHS data announcement, as it seems a natural follow to that news. If the DHHS data is planned for later than Wednesday, we could put it out by itself. Like I said, we're testing a couple schools every weekend these days, so we'll have more after this announcement and the findings are all following the same pattern.

b

From: Krisztian, George (DEQ)
Sent: Monday, November 30, 2015 1:09 PM
To: Tommasulo, Karen (DEQ); Wurfel, Brad (DEQ); Shaw, Eric (DEQ)
Subject: RE: Eisenhower

Attached is the final version of the Eisenhower report.

George L. Krisztian
 Flint Action Plan Coordinator
 Laboratory Director
 Michigan Department of Environmental Quality
 Desk ph (517) 284-6719
 Cell ph PPI

From: Tommasulo, Karen (DEQ)
Sent: Monday, November 30, 2015 11:55 AM
To: Wurfel, Brad (DEQ); Shaw, Eric (DEQ); Krisztian, George (DEQ)
Subject: Eisenhower

This is the latest I have for the Eisenhower data. George, do you know of a more updated version?

Karen Tommasulo
 Public Information Officer

Michigan Department of Environmental Quality

517-284-6716 | 517-599-5733

tommasulok@michigan.gov