

Thank you Mary.

On Oct 21, 2015 12:28 PM, "Mary Lynn Semegen" <[semegen@dwsd.org](mailto:semegen@dwsd.org)> wrote:  
The Lake Huron plant tap residual ortho-phosphate is 1.0-1.2 ppm.

Sincerely,

Mary Lynn Semegen, Manager  
Water Quality Division  
Detroit Water and Sewerage Department  
Water Works Park Plant  
Room 208  
10100 E. Jefferson  
Detroit, Michigan 48214  
Phone: 313 926-8102  
FAX: 313 842-6418  
[semegen@dwsd.org](mailto:semegen@dwsd.org)

City of Detroit  
Mike Duggan, Mayor

On 10/21/2015 11:27 AM, Brent Wright wrote:  
Mary

Do you know the feed in ppm that is coming from the Burtchville plant? We were under the impression the plant was only feeding a maintenance level of .4 to .5ppm. Our lab analysis show this to be higher.

Thank you

--  
**Brent Wright**  
**Water Plant Supervisor**  
**City of Flint**  
**4500 N. Dort Hwy.**  
**Flint, MI. 48505**  
**Ph: 810.787.6537 ext. 3510**  
**Fx: 810.787.3710**

--  
**Brent Wright**  
**Water Plant Supervisor**  
**City of Flint**  
**4500 N. Dort Hwy.**  
**Flint, MI. 48505**  
**Ph: 810.787.6537 ext. 3510**  
**Fx: 810.787.3710**

use, disclosure or copying of this Communication is strictly prohibited. If you have received this Communication in error, please contact the sender immediately and destroy any and all copies of this Communication.