
From: Prysby, Mike (DEQ)
Sent: Wednesday, June 10, 2015 10:40 AM
To: Michael Glasgow
Subject: RE: Lead-Copper info

Thanks Michael

Michael Prysby, P.E.
District Engineer
Office of Drinking Water and Municipal Assistance
517 290-8817

From: Michael Glasgow [<mailto:mglasgow@cityofflint.com>]
Sent: Wednesday, June 10, 2015 10:37 AM
To: Prysby, Mike (DEQ)
Subject: Re: Lead-Copper info

Mike,

To answer your questions:

1. I'm trying to compile the list.
2. There were a couple of Apartment residences that were used in the first sampling pool. These would be tier 2 sites. the majority were Tier 1.
3. A copy of the consumer notice is attached below.
4. This was in response to a customer complaint, and it is a business. I would only use the Utility sink as a site if we are short a sample, and would be a Tier 3. This is not in our sample pool, but is served by lead service line.

On Tue, Jun 9, 2015 at 10:14 AM, Prysby, Mike (DEQ) <PRYSBYM@michigan.gov> wrote:

Mike,

I was trying to contact you regarding Lead and Copper info that we may need. I don't have your cell number...and the WTP main phone was not switching over to the option to have my incoming call forwarded to the lab. I wish to discuss the following:

1. Basically, we need a listing of Flint's PB&CU sampling pool (around 120 sites) with the Tier designation (Tier 1, Tier 2, or Tier 3) and those sites with lead services. It is possible that

you may have sent us this information last summer as part of revising the lead & copper monitoring program.

2. The lead & copper reporting form for the July 2014 – Dec 2014 monitoring period states that not all sites were Tier 1; however, the listing of all 100 locations on the subsequent pages show all locations being Tier 1. Please clarify
3. Please provide us a copy of the consumer lead notice that was mailed to each customer in your sampling pool....we only need a copy of one notice.
4. We have received 28 of the 100 samples for the Jan-June 2015 round of lead/copper monitoring. Four of the samples were above the lead action level; however the PURPOSE of monitoring for two of these was noted as "OTHER" instead of ROUTINE MONITORING. The address of these 2 locations are: 625 S. Grand Traverse (Utility Sink) and 625 S. Grand Traverse (Bathroom). Is this site part of the sampling pool or was this location sampled based on a customer complaint and/or concern?

Michael Prysby, P.E.

District Engineer

Office of Drinking Water and Municipal Assistance

517 290-8817

—
Mike Glasgow
Utilities Administrator
City of Flint